


QUICK TOOLS - MOLDING SCRAPER



Draw Block for Beading Planks





Make a Molding on a Mill

Take Proper
Safety Precautions

- 1. Clamp guide to table
- 2. Position cutter:
 - End Mill or
 - Special Cutter
- 3. Push/Pull wood strip past cutter

